SICK

DGS35-1KK02048

Part Number: [illegible] / [illegible]: [illegible]

Datasheets: [illegible]

DGS35-1KK02048

SICK

ROTARY ENCODR INCREMENT 2048PPR

[illegible]

DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION

[illegible] DGS35-1KK02048

PART NUMBER	DGS35-1KK02048
[illegible]	SICK
[illegible]	ROTARY ENCODR INCREMENT 2048PPR
[illegible] / [illegible] ROHS	
VOLTAGE-SUPPLY	4.5 V ~ 5.5 V
[illegible]	Cable
SERIES	-
[illegible] ([illegible])	-
[illegible]	2048
[illegible]	-
[illegible]	1077268
[illegible]	User Selectable
MOUNTING TYPE	Chassis Mount
[illegible]	3 Weeks
[illegible] ENCODER	Incremental
DETENT	No
BUILT IN SWITCH	No
[illegible]	Hole for Shaft

Related Tags

- SICK DGS35-1KK02048
- [illegible] DGS35-1KK02048
- [illegible] DGS35-1KK02048
- [illegible] DGS35-1KK02048
- [illegible] DGS35-1KK02048
- [illegible] DGS35-1KK02048
- [illegible] DGS35-1KK02048 PDF
- DGS35-1KK02048 [illegible] Datasheet
- [illegible] DGS35-1KK02048
- [illegible] DGS35-1KK02048
- [illegible] DGS35-1KK02048
- SICK DGS35-1KK02048
- SICK DGS35-1KK02048
- [illegible] SICK
- [illegible] SICK
- SICK DGS35-1KK02048

[illegible]

DGS35-1KK01024

[illegible]: SICK
[illegible]: ROTARY ENCODR INCREMENT 1024PPR
[illegible]: Out stock

RFQ

DGS35-1J405000

[illegible]: SICK
[illegible]: ROTARY ENCODR INCREMENT 5000PPR
[illegible]: Out stock

RFQ

DGS35-1KN02048

[illegible]: SICK
[illegible]: ROTARY ENCODR INCREMENT 2048PPR
[illegible]: Out stock

RFQ

DGS35-1KK02500

[illegible]: SICK
[illegible]: ROTARY ENCODR INCREMENT 2500PPR
[illegible]: Out stock

RFQ

DGS35-1JK04096

[illegible]: SICK
[illegible]: ROTARY ENCODR INCREMENT 4096PPR
[illegible]: Out stock

RFQ

DGS35-1J202048

[illegible]: SICK
[illegible]: ROTARY ENCODR INCREMENT 2048PPR
[illegible]: Out stock

RFQ

DGS35-1K200120

[illegible]: SICK
[illegible]: ROTARY ENCODR INCREMENTAL 120PPR
[illegible]: Out stock

RFQ

DGS35-1L202048

[illegible]: SICK
[illegible]: ROTARY ENCODR INCREMENT 2048PPR
[illegible]: Out stock

RFQ

DGS35-1KK05000

[illegible]: SICK
[illegible]: ROTARY ENCODR INCREMENT 5000PPR
[illegible]: Out stock

RFQ

DGS35-1L202500

[illegible]: SICK
[illegible]: ROTARY ENCODR INCREMENT 2500PPR
[illegible]: Out stock

RFQ

DGS35-1K405000

[illegible]: SICK
[illegible]: ROTARY ENCODR INCREMENT 5000PPR
[illegible]: Out stock

RFQ

DGS35-1L204096

[illegible]: SICK
[illegible]: ROTARY ENCODR INCREMENT 4096PPR
[illegible]: Out stock

RFQ

© 2020 [illegible] - Ocean-Components.com

[illegible]: Info@Ocean-Components.com

[illegible]: Room 2102, Connaught Commercial Building, 185 Wan Chai Rd, Wan Chai, Hong Kong